Asus Eee PC 1000HA Screen Replacement

This guide will show you how to replace the screen.

Written By: Ashlee Stickle



INTRODUCTION

In this guide we will provide you with the necessary information to replace the screen on an Asus Eee PC 1000HA.

TOOLS:

- Phillips #00 Screwdriver (1)
- Metal Spudger (1)
- Magnetic Project Mat (1)
- Tweezers (1)


Step 1 — Screen






- Remove the battery before working on your device. See this LINK for a step-by-step guide.
- Use the metal tweezers to remove all of the rubber pads from the face of the lap top.
- Removing the rubber pads will reveal 6 screws.

Step 2



- Use a #00 Phillips Head screw driver to remove the 4.8mm screws.
- There will be 6 screws total.

Step 3






- Use the metal spudger to pry off the outside frame of the screen.

Step 4



- Use the #00 Phillips Head screw driver to remove the 5.44mm screws.
- There are 6 screws total.



Step 5





- Use the metal spudger to gently remove the screen from the laptop.

Step 6


- Gently pull the tab that is connecting the laptop to the screen, to fully disconnect the screen from the laptop.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-23 08:13:58 AM.

